



Fence Master INC	Description	Cost
Centennial #1	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #2	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #3	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,625.00
Centennial #4	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #5	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #6	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #7	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Centennial #8	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,625.00
Centennial #9	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00
Dog Park Fencing	Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,375.00
Fence By Volleyball Court	Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,375.00

Ice Rink	Remove wood split rail/ Replace with PVC Split Rail Fence (3 Rails)/ 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$17,400.00
Pool Area	Bathroom Areas Installing 40 lineal feet of western red cedar privacy fencing. There will be (4) 2" x 6" cedar rails per panel. Rails to be toe nailed to middle of posts using joist hangers so they will not be visible on either side of fence. Privacy pickets to be installed on the inside and outside of both areas. There will be a 1" x 6" face nailed at the top and bottom of each panel on the inside and outside of each area. Village of Orland Park responsible for the tear down of existing fences Full length pickets to be used on either height	\$10,070.00
Pool Area 2	Dumpster Area Installing 17 lineal feet of western red cedar privacy fencing. Included in the footage is (1) 4' wide steel framed gate with cedar privacy pickets attached to the outside of frame. There will be (4) 2" x 6" cedar rails per panel. Rails to be face nailed to cedar posts. There will be a 1" x 6" faced nailed at the top and bottom of each panel.	\$4,280.00
Sledding Hill Addition	Add 110ft of split rail fence from walk path north of sledding hill to the south and base of the sledding hill. 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$5,500.00
Sledding Hill	Remove log split rail/ Replace with PVC Split Rail Fence (3 Rails)/ 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$6,750.00
	Total Awarded	\$59,275.00