

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9999 143rd Street

**Common Name** Old Methodist Church

**Historic Name** Christ Evangelical Lutheran Church

**Current Use** Commercial

**Historic Use** Religious

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9999 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Gothic Revival

**Number of Stories** 1+

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with conical tower

**Window Type & Materials** Original stained glass within the gothic arched window above door; remaining gothic arched windows are replacements with applied muntins

**Porch**

**Architectural Details** Projecting center tower is square with vented openings toward the top and with scrolled brackets under the eaves; Gothic arch window openings; gothic arch window over main entrance door;

**Alterations** Synthetic siding; windows have been replaced; front door has been altered; there is a large addition at the side toward the rear

## HISTORY

**Original Construction Date** 1898 per wall plaque

**Architect/Builder**

**Associated Events, People, Dates** Built in 1898 for the Christ Evangelical Lutheran Church, the last congregation in the church was the Presbyterian Church which purchased the building in 1975

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9999 143rd Street, west of corner



9999 143rd St\_rectory.jpg

**Common Name** Realty Executives

**Historic Name** Rectory

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Hipped

**Number of Stories** 1

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood 3/1 light, double-hung windows

**Porch** Open wood front porch with front gabled roof, square posts

**Architectural Details** Brick interior chimney

**Alterations**

## HISTORY

**Original Construction Date** 1903 per church building plaque **Architect/Builder**

**Associated Events, People, Dates** This house served as the rectory to the adjacent church

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9960 143rd Street

**Common Name** Park Avenue School & Gym

**Historic Name** Orland Park School

**Current Use** School

**Historic Use** School

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9960 143rd St\_9.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Prairie with Georgian Revival features

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Hipped

**Window Type & Materials** Wood, 4/4 vertically divided light, double-hung windows; some windows have three sash, each with 4 vertically divided lights; smaller 3/3 vertically divided light windows

**Porch**

**Architectural Details** Horizontal emphasis; center raised entrance with pedimented gable; double doors with sidelights, arched transoms and limestone key details in the brick arch; original wall mounted light fixtures; limestone plaque which reads "Orland Park School"; there is a semi-circular, divided light window within the pedimented gable; the ribbon windows have limestone sills

**Alterations** There is a 1940 Joliet limestone gymnasium addition to the west and a steel and glass, International style addition to the east

## HISTORY

**Original Construction Date** 1922 per wall plaque

**Architect/Builder** Architect: Alfred E. Pashley, source: Village of Orland Park

**Associated Events, People, Dates** The 1940 gymnasium addition was designed by an architect by the name of Pomeroy, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

## Continuation Sheet

**Address** 9960 143rd Street

**Map Key** B- 10



9960 143rd St\_Addition.jpg



9960 143rd St\_international addition.jpg

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9953 143rd Street

**Common Name**

**Historic Name**

**Current Use** Commercial

**Historic Use** Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9953 143rd St.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** National: Gable-Front with Folk Victorian details

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Metal 1/1 light double-hung

**Porch** Wood, open porch with turned posts and balusters; front gable roof with wood shingles in the gable

**Architectural Details** Wood shingles in the gable of the house and of the porch; original window frames remain with squared, decorative window hoods

**Alterations** New front door; replacement windows; new concrete ramp from sidewalk to front door

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9925 143rd Street

**Common Name**

**Historic Name**

**Current Use** Retail

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9925 143rd St\_4.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Italianate

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Composition shingle

**Roof** Asphalt shingle

**Roof Type** Front gable

**Window Type & Materials** Wood 2/2 vertically divided light, double-hung windows; Queen Anne window at first floor

**Porch** Open, wood porch with turned posts and squared balusters; hipped roof

**Architectural Details** Arched window hoods at second floor of primary elevation; secondary elevations have pedimented window hoods; transom over front door; wood decorative trim and circular window at the gable

**Alterations** Composition siding; non-original shutters

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9917 143rd Street

**Common Name** Elia's Day Spa / Allstate

**Historic Name**

**Current Use** Commercial

**Historic Use** Commercial

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



9917 143rd St\_3.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Tudor Revival

**Number of Stories** 1

**Materials**

**Foundation** Not Visible

**Walls** Brick

**Roof** Asphalt shingle

**Roof Type** Gable-on-hip

**Window Type & Materials** Wood, fixed picture windows

**Porch**

**Architectural Details** Arched masonry detail around doors including irregular limestone arch stones; irregular facade heights, entrance gables and roof forms; limestone window sills; window transoms covered over

**Alterations** Transoms blocked; new awnings and lighting mounted to the brick facade; doors replaced

## HISTORY

**Original Construction Date** c1935

**Architect/Builder**

**Associated Events, People, Dates** Served as Orland Park's first Public Library, source: Village of Orland Park

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14306-14310 Union Avenue

**Common Name** Old Orland Insurance

**Historic Name** Orland Park Hotel

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14306-10 Union Ave.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront / Italianate

**Number of Stories** 2+

**Materials**

**Foundation** Brick

**Walls** Wood clapboard; synthetic

**Roof** Asphalt shingles

**Roof Type** Front gable with false facade front

**Window Type & Materials** Wood 1/1 double-hung; wood 2/2 vertical light double-hung; storefronts: fixed divided lights

**Porch**

**Architectural Details** False facade front with Italianate details; cornice has paired, carved brackets and dentils under the eave; segmental arch window hoods at front and squared window hoods at sides; cornice above first floor has carved brackets and dentils under the eave; uppermost center window opening has paired arched topped windows

**Alterations** Synthetic siding; storefronts have been altered; doors altered; transom over door covered

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14314 Union Avenue

**Common Name** Union Avenue General Store

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Commercial/Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14314 Union Ave\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Commercial / Storefront / Italianate

**Number of Stories** 2

**Materials**

**Foundation** Limestone; parged; brick at additions

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable with squared false facade front; residential additions are side gable with hipped porch roofs

**Window Type & Materials** Wood fixed windows at storefronts with original bulkheads and paired wood doors and transoms; wood 1/1 double-hung windows; residential addition has Queen Anne window

**Porch** Open porch with turned wood posts and hipped roof

**Architectural Details**

**Alterations** Synthetic siding; window hoods have been removed; early residential addition

## HISTORY

**Original Construction Date** c1885

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14315 Beacon Avenue

**Common Name** Touch of Class Pet Grooming

**Historic Name**

**Current Use** Commercial/Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14315 Beacon.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Folk Victorian

**Number of Stories** 2

**Materials**

**Foundation** Not Visible

**Walls** Synthetic siding

**Roof** Asphalt shingle

**Roof Type** Front gable; hipped roof over porch

**Window Type & Materials** Wood, double-hung with 2/2 verticle lights; metal picture window; Queen Anne window with transom at the side of the house

**Porch** "L" shaped porch with turned wood posts, squared balusters, spindlework porch detailing, wide wood steps and hipped roof

**Architectural Details** Original decorative window hoods and casing with incised design, bullseye corner blocks and stepped wood window hood; same wood detail surrounds the front door; interior brick chimney

**Alterations** Siding altered; some windows replaced

## HISTORY

**Original Construction Date** c1890

**Architect/Builder**

**Associated Events, People, Dates**

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 9967 144th Street

**Common Name** United Methodist Church

**Historic Name** Twin Towers Church

**Current Use** Social / Religious

**Historic Use** Religious

**Integrity** High

**Condition** Good

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** Yes



9967 144th St\_2.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** Queen Anne

**Number of Stories** 1+ towers

**Materials**

**Foundation** Formed concrete block

**Walls** Wood clapboard; wood decorative shingles

**Roof** Asphalt shingle

**Roof Type** Front gable with conical, bell shaped towers

**Window Type & Materials** Wood 1/1 light double-hung pointed arch; wood 1/1 light double-hung round arch; opaque glass (opaque glass installed in 1940 which replaced clear glass)

**Porch**

**Architectural Details** Wood clapboard, diamond and fishscale shingles; carved brackets under wide eaves; pointed and round arched windows; circular window under front gable; two octagonal towers

**Alterations** Foundation raised (1918), stone foundation replaced with concrete block raised foundation; center entry constructed in 1942 and removed sometime after 1991; large snactuary addition to the west (1961); raised east entry added sometime after 1991

## HISTORY

**Original Construction Date** 1898 per plaque

**Architect/Builder** Architect: William Arthur Bennett

**Associated Events, People, Dates** Listed on the National Register of Historic Places; significant dates for the building: 1898 & 1918. Interior has a Sullivanesque pressed metal ceiling

**Surveyor** PV

**Date** 10/4/2005



# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 14316 Beacon Avenue

**Common Name** Old Bank Antiques

**Historic Name** Orland State Bank

**Current Use** Retail/Residential

**Historic Use** Commercial/Residential

**Integrity** High

**Condition** Excellent

**Local Landmark**

**Individual** No

**Old Orland Historic District** Contributing

**National Register**

**Individual** No



14316 Beacon\_7.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

1984 Residential Survey, 1991 Residential Survey

**Architectural Type/Style** 20th Century Commercial / Italianate

**Number of Stories** 2

**Materials**

**Foundation** Parged

**Walls** Brick

**Roof** Built-up bituminous

**Roof Type** Flat

**Window Type & Materials** Wood double-hung 1/1 light; wood fixed; transoms with divided light pattern

**Porch**

**Architectural Details** Limestone sills and lintels; limestone ornament at parapet; corbelled brick at parapet capped with limestone; corbelled chimney detail at side of building; painted cornice at first floor; original wood door frames; historic door to commercial space; original wood windows

**Alterations**

## HISTORY

**Original Construction Date** 1920 per limestone marker

**Architect/Builder**

**Associated Events, People, Dates**

**Surveyor** PV

**Date** 10/4/2005

# Village of Orland Park, Illinois Historic Buildings Survey

**Address** 10117 143rd Street

**Map Key** B- 18

**Common Name**

**Historic Name**

**Current Use** Residential

**Historic Use** Residential

**Integrity** Medium

**Condition** Good

**Local Landmark**

**Individual** Eligible

**Old Orland Historic District** N/A

**National Register**

**Individual** No



10117 143rd Street.jpg

## DESCRIPTION

**Inclusion in Previous Surveys**

**Architectural Type/Style** Craftsman

**Number of Stories** 1 1/2

**Materials**

**Foundation** Formed concrete block; porch foundation not visible

**Walls** Synthetic siding

**Roof** Asphalt shingles

**Roof Type** Gable

**Window Type & Materials** Wood: 4/1, 3/1 7 single light

**Porch** Retains original integral porch with three sides of windows and paneled porch door with multi-paned divided lights, and sidelights

**Architectural Details** Rafter tails; shed roof dormer; integral porch with original windows

**Alterations** Siding, front deck and steps

## HISTORY

**Original Construction Date** c1915

**Architect/Builder**

**Associated Events, People, Dates**