

Village of Orland Park, Illinois

Historic Buildings Survey

Address 9999 143rd Street

Common Name Old Methodist Church

Historic Name Christ Evangelical Lutheran Church

Current Use Commercial

Historic Use Religious

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9999 143rd St_3.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Gothic Revival

Number of Stories 1+

Materials

Foundation Not Visible

Walls Synthetic siding

Roof Asphalt shingle

Roof Type Front gable with conical tower

Window Type & Materials Original stained glass within the gothic arched window above door; remaining gothic arched windows are replacements with applied muntins

Porch

Architectural Details Projecting center tower is square with vented openings toward the top and with scrolled brackets under the eaves; Gothic arch window openings; gothic arch window over main entrance door;

Alterations Synthetic siding; windows have been replaced; front door has been altered; there is a large addition at the side toward the rear

HISTORY

Original Construction Date 1898 per wall plaque

Architect/Builder

Associated Events, People, Dates Built in 1898 for the Christ Evangelical Lutheran Church, the last congregation in the church was the Presbyterian Church which purchased the building in 1975

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 9999 143rd Street, west of corner

Common Name Realty Executives

Historic Name Rectory

Current Use Commercial

Historic Use Residential

Integrity High

Condition Excellent

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9999 143rd St_rectory.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style National: Hipped

Number of Stories 1

Materials

Foundation Formed concrete block

Walls Wood clapboard

Roof Asphalt shingle

Roof Type Hipped

Window Type & Materials Wood 3/1 light, double-hung windows

Porch Open wood front porch with front gabled roof, square posts

Architectural Details Brick interior chimney

Alterations

HISTORY

Original Construction Date 1903 per church building plaque **Architect/Builder**

Associated Events, People, Dates This house served as the rectory to the adjacent church

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois

Historic Buildings Survey

Address 9960 143rd Street

Common Name Park Avenue School & Gym

Historic Name Orland Park School

Current Use School

Historic Use School

Integrity High

Condition Excellent

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9960 143rd St_9.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Prairie with Georgian Revival features

Number of Stories 2

Materials

Foundation Parged

Walls Brick

Roof Asphalt shingle

Roof Type Hipped

Window Type & Materials Wood, 4/4 vertically divided light, double-hung windows; some windows have three sash, each with 4 vertically divided lights; smaller 3/3 vertically divided light windows

Porch

Architectural Details Horizontal emphasis; center raised entrance with pedimented gable; double doors with sidelights, arched transoms and limestone key details in the brick arch; original wall mounted light fixtures; limestone plaque which reads "Orland Park School"; there is a semi-circular, divided light window within the pedimented gable; the ribbon windows have limestone sills

Alterations There is a 1940 Joliet limestone gymnasium addition to the west and a steel and glass, International style addition to the east

HISTORY

Original Construction Date 1922 per wall plaque

Architect/Builder Architect: Alfred E. Pashley, source: Village of Orland Park

Associated Events, People, Dates The 1940 gymnasium addition was designed by an architect by the name of Pomeroy, source: Village of Orland Park

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Continuation Sheet

Address 9960 143rd Street

Map Key B- 10



9960 143rd St_Addition.jpg



9960 143rd St_international addition.jpg

Village of Orland Park, Illinois Historic Buildings Survey

Address 9953 143rd Street

Common Name

Historic Name

Current Use Commercial

Historic Use Residential

Integrity High

Condition Excellent

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9953 143rd St.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style National: Gable-Front with Folk Victorian details

Number of Stories 1 1/2

Materials

Foundation Formed concrete block

Walls Wood clapboard; wood shingle

Roof Asphalt shingle

Roof Type Front gable

Window Type & Materials Metal 1/1 light double-hung

Porch Wood, open porch with turned posts and balusters; front gable roof with wood shingles in the gable

Architectural Details Wood shingles in the gable of the house and of the porch; original window frames remain with squared, decorative window hoods

Alterations New front door; replacement windows; new concrete ramp from sidewalk to front door

HISTORY

Original Construction Date c1890

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 9925 143rd Street

Common Name

Historic Name

Current Use Retail

Historic Use Residential

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9925 143rd St_4.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Italianate

Number of Stories 2

Materials

Foundation Parged

Walls Composition shingle

Roof Asphalt shingle

Roof Type Front gable

Window Type & Materials Wood 2/2 vertically divided light, double-hung windows; Queen Anne window at first floor

Porch Open, wood porch with turned posts and squared balusters; hipped roof

Architectural Details Arched window hoods at second floor of primary elevation; secondary elevations have pedimented window hoods; transom over front door; wood decorative trim and circular window at the gable

Alterations Composition siding; non-original shutters

HISTORY

Original Construction Date c1885

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 9917 143rd Street

Common Name Elia's Day Spa / Allstate

Historic Name

Current Use Commercial

Historic Use Commercial

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



9917 143rd St_3.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Tudor Revival

Number of Stories 1

Materials

Foundation Not Visible

Walls Brick

Roof Asphalt shingle

Roof Type Gable-on-hip

Window Type & Materials Wood, fixed picture windows

Porch

Architectural Details Arched masonry detail around doors including irregular limestone arch stones; irregular facade heights, entrance gables and roof forms; limestone window sills; window transoms covered over

Alterations Transoms blocked; new awnings and lighting mounted to the brick facade; doors replaced

HISTORY

Original Construction Date c1935

Architect/Builder

Associated Events, People, Dates Served as Orland Park's first Public Library, source: Village of Orland Park

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 14306-14310 Union Avenue

Common Name Old Orland Insurance

Historic Name Orland Park Hotel

Current Use Commercial/Residential

Historic Use Commercial/Residential

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



14306-10 Union Ave.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Commercial / Storefront / Italianate

Number of Stories 2+

Materials

Foundation Brick

Walls Wood clapboard; synthetic

Roof Asphalt shingles

Roof Type Front gable with false facade front

Window Type & Materials Wood 1/1 double-hung; wood 2/2 vertical light double-hung; storefronts: fixed divided lights

Porch

Architectural Details False facade front with Italianate details; cornice has paired, carved brackets and dentils under the eave; segmental arch window hoods at front and squared window hoods at sides; cornice above first floor has carved brackets and dentils under the eave; uppermost center window opening has paired arched topped windows

Alterations Synthetic siding; storefronts have been altered; doors altered; transom over door covered

HISTORY

Original Construction Date c1885

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois

Historic Buildings Survey

Address 14314 Union Avenue

Common Name Union Avenue General Store

Historic Name

Current Use Commercial/Residential

Historic Use Commercial/Residential

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



14314 Union Ave_2.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Commercial / Storefront / Italianate

Number of Stories 2

Materials

Foundation Limestone; parged; brick at additions

Walls Synthetic siding

Roof Asphalt shingle

Roof Type Front gable with squared false facade front; residential additions are side gable with hipped porch roofs

Window Type & Materials Wood fixed windows at storefronts with original bulkheads and paired wood doors and transoms; wood 1/1 double-hung windows; residential addition has Queen Anne window

Porch Open porch with turned wood posts and hipped roof

Architectural Details

Alterations Synthetic siding; window hoods have been removed; early residential addition

HISTORY

Original Construction Date c1885

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 14315 Beacon Avenue

Common Name Touch of Class Pet Grooming

Historic Name

Current Use Commercial/Residential

Historic Use Residential

Integrity Medium

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



14315 Beacon.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Folk Victorian

Number of Stories 2

Materials

Foundation Not Visible

Walls Synthetic siding

Roof Asphalt shingle

Roof Type Front gable; hipped roof over porch

Window Type & Materials Wood, double-hung with 2/2 verticle lights; metal picture window; Queen Anne window with transom at the side of the house

Porch "L" shaped porch with turned wood posts, squared balusters, spindlework porch detailing, wide wood steps and hipped roof

Architectural Details Original decorative window hoods and casing with incised design, bullseye corner blocks and stepped wood window hood; same wood detail surrounds the front door; interior brick chimney

Alterations Siding altered; some windows replaced

HISTORY

Original Construction Date c1890

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois

Historic Buildings Survey

Address 9967 144th Street

Common Name United Methodist Church

Historic Name Twin Towers Church

Current Use Social / Religious

Historic Use Religious

Integrity High

Condition Good

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual Yes



9967 144th St_2.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style Queen Anne

Number of Stories 1+ towers

Materials

Foundation Formed concrete block

Walls Wood clapboard; wood decorative shingles

Roof Asphalt shingle

Roof Type Front gable with conical, bell shaped towers

Window Type & Materials Wood 1/1 light double-hung pointed arch; wood 1/1 light double-hung round arch; opaque glass (opaque glass installed in 1940 which replaced clear glass)

Porch

Architectural Details Wood clapboard, diamond and fishscale shingles; carved brackets under wide eaves; pointed and round arched windows; circular window under front gable; two octagonal towers

Alterations Foundation raised (1918), stone foundation replaced with concrete block raised foundation; center entry constructed in 1942 and removed sometime after 1991; large snactuary addition to the west (1961); raised east entry added sometime after 1991

HISTORY

Original Construction Date 1898 per plaque

Architect/Builder Architect: William Arthur Bennett

Associated Events, People, Dates Listed on the National Register of Historic Places; significant dates for the building: 1898 & 1918. Interior has a Sullivanesque pressed metal ceiling

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois

Historic Buildings Survey

Address 14316 Beacon Avenue

Common Name Old Bank Antiques

Historic Name Orland State Bank

Current Use Retail/Residential

Historic Use Commercial/Residential

Integrity High

Condition Excellent

Local Landmark

Individual No

Old Orland Historic District Contributing

National Register

Individual No



14316 Beacon_7.jpg

DESCRIPTION

Inclusion in Previous Surveys

1984 Residential Survey, 1991 Residential Survey

Architectural Type/Style 20th Century Commercial / Italianate

Number of Stories 2

Materials

Foundation Parged

Walls Brick

Roof Built-up bituminous

Roof Type Flat

Window Type & Materials Wood double-hung 1/1 light; wood fixed; transoms with divided light pattern

Porch

Architectural Details Limestone sills and lintels; limestone ornament at parapet; corbelled brick at parapet capped with limestone; corbelled chimney detail at side of building; painted cornice at first floor; original wood door frames; historic door to commercial space; original wood windows

Alterations

HISTORY

Original Construction Date 1920 per limestone marker

Architect/Builder

Associated Events, People, Dates

Surveyor PV

Date 10/4/2005

Village of Orland Park, Illinois Historic Buildings Survey

Address 10117 143rd Street

Map Key B- 18

Common Name

Historic Name

Current Use Residential

Historic Use Residential

Integrity Medium

Condition Good

Local Landmark

Individual Eligible

Old Orland Historic District N/A

National Register

Individual No



10117 143rd Street.jpg

DESCRIPTION

Inclusion in Previous Surveys

Architectural Type/Style Craftsman

Number of Stories 1 1/2

Materials

Foundation Formed concrete block; porch foundation not visible

Walls Synthetic siding

Roof Asphalt shingles

Roof Type Gable

Window Type & Materials Wood: 4/1, 3/1 7 single light

Porch Retains original integral porch with three sides of windows and paneled porch door with multi-paned divided lights, and sidelights

Architectural Details Rafter tails; shed roof dormer; integral porch with original windows

Alterations Siding, front deck and steps

HISTORY

Original Construction Date c1915

Architect/Builder

Associated Events, People, Dates

Surveyor PV/DE

Date 3/19/2008