



ORLAND PARK

Bid Tabulation

Bid Number: 17-022

Bid Issue: April 21, 2017

Bid Opening: May 5, 2017

Project Title: Centennial Park Fence Repair/Replacement

Department: Parks & Grounds

Addenda:

BIDDER	GRAND TOTAL BID PRICE	CONTACT INFORMATION
Fence Masters, Inc	\$72,275.00	Pter Biancardi 20400 S. Cottage Grove Ave Chicago Heights, IL 60111 P: 708-758-5250/F: 708-758-5251 Email: pbiancardi@fencemastersinc.com
America's Backyard	bid per unit pricing	Chris Dohner 1909 S. Briggs St. Joliet, IL 60433 P:815-419-1194/F: 815-834-1589 Email: chris@americasbackyard.com

Bids are subject to review for completeness, accuracy, and compliance with all terms and conditions of the bid specifications

Prepared by: Denise Domalewski, Purchasing Administrator - Village of Orland Park

Village of Orland Park Bid Responsiveness Check

Bid #: 17-022

Project Title: Centennial Park Fence Repair/Replacement

Bid Requirement	Fence Masters	America's Backyard			
Submitted three (3) sealed hardcopies of the bid	√	√			
Submitted a completed Bidder Summary Sheet	√	v1			
Submitted a completed Affidavit of Compliance	√	v2			
Submitted three (3) references	√	√			
Submitted signed Insurance Requirements form	√	√			
Unit Price Sheet	√	√			
Proposed amount	\$72,275.00	unit pricing			

**A check mark in the box indicates inclusion of the required form with the proposal package. A "V#" indicates a variance that will be explained below.*

v1 - Did not include Total Bid Price - provided a separate letter with per piece pricing

v2 - does not participate in AT&T program

Prepared by:Denise Domalewski, Purchasing Administrator - Village of Orland Park

Location/Field#	Description of Damage	Fence Masters Cost	America's Backyard Cost
Centennial #1	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #2	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #3	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,625.00	see breakdown
Centennial #4	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #5	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #6	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #7	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Centennial #8	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,625.00	see breakdown

Location/Field#	Description of Damage	Fence Masters Cost	America's Backyard Cost
Centennial #9	Outfield Homerun Fence: Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,325.00	see breakdown
Sledding Hill	Remove log split rail/ Replace with PVC Split Rail Fence (3 Rails)/ 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$6,750.00	see breakdown
Ice Rink	Remove wood split rail/ Replace with PVC Split Rail Fence (3 Rails)/ 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$17,400.00	\$6,620.00
West Side Field #4	Remove wood split rail/ Replace with PVC Split Rail Fence (3 Rails)/ 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$13,000.00	\$4,620.00
Fence By Volleyball Court	Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,375.00	see breakdown
Pool Area	Bathroom Areas Installing 40 lineal feet of western red cedar privacy fencing. There will be (4) 2" x 6" cedar rails per panel. Rails to be toe nailed to middle of posts using joist hangers so they will not be visible on either side of fence. Privacy pickets to be installed on the inside and outside of both areas. There will be a 1" x 6" face nailed at the top and bottom of each panel on the inside and outside of each area. Village of Orland Park responsible for the tear down of existing fences Full length pickets to be used on either height	\$10,070.00	\$6,500.00

Location/Field#	Description of Damage	Fence Masters Cost	America's Backyard Cost
Pool Area 2	<p>Dumpster Area</p> <p>Installing 17 lineal feet of western red cedar privacy fencing. Included in the footage is (1) 4' wide steel framed gate with cedar privacy pickets attached to the outside of frame. There will be (4) 2" x 6" cedar rails per panel. Rails to be face nailed to cedar posts. There will be a 1" x 6" faced nailed at the top and bottom of each panel.</p>	\$4,280.00	\$3,160.00
Dog Park Fencing	Re-Set all heaved fence posts (match existing materials)/ Repair any damaged top rail, bottom rail missing ties and hardware (match existing materials)/ Replace Damaged fencing (bent, jagged, unserviceable) match existing material	\$1,375.00	see breakdown
Sledding Hill Addition	Add 110ft of split rail fence from walk path north of sledding hill to the south and base of the sledding hill. 5x5 posts, and 2x8 ribbed rails. The color is Adobe and it is manufactured by Homeland Vinyl. All holes are dug to a depth of 42" and a weep hole is cut in the posts for additional security against heaving.	\$5,500.00	\$2,420.00
Grand Total Bid Price (Please enter total on Bidder Summary Sheet)		\$72,275.00	\$ _____

America's Backyard Breakdown

\$160 per post
 \$4 per foot for top rail
 \$10 per foot for fabric
 \$2 per tie