

## **Revised Quotation**

Company: <u>\</u>	Village of Orland Park		_	Model:	IT28	BG .				
Attn:	Tom Morgan	Account No: 2795000		Serial No:	8CR	2513				
E-Mail: 1	tmorgan@orland-park.il.us		_	Service Meter:	2075	5				
_	708-362-2370	Fax:		omer Unit No:		-				
_		- CAN.	Odot	511101 O1110 140.						
Original Date:		5								
Revised Date: 2	25-Oct-11	Revision: 1 Of 1								
	01	land Our in a			1	Labas	1	N. A		T-1-1
Inancet Machine		lard Services				Labor		Misc.		Total
	/ Scheduled Oil Samples				d.	120.00			\$	120.00
<ul><li>✓ Cleaning Charges</li><li>✓ Environmental</li></ul>	5				\$	120.00			Þ	120.00
✓ Misc.							\$	29.50	¢	29.50
IVII3C.							Ψ	Sub-Total:	Ψ	149.50
								oub-Total.		149.50
Addition Items				Labor		Parts		Misc.		Amount
	rms for straightening or repla	acement. Inspect upper lift arm pins and	\$ t	1,696.50					\$	1,696.50
		rms pins may need to be cut out and								
		Inspect loader frame for any possible								
	es removed and repienisn ny r labor needed to complete	rdraulic oil. ***Customer will be								
notined of any parts of	riabor needed to complete	e repairs.								
•		ess as needed. Both arms bent	\$	3,290.00	\$	554.22			\$	3,844.22
1.5".Replace damaged lo	ower bearings, seals, and pi	ns.								
Repair crack in loader a	rm- cracked at right arm/ cro	ss member junction	\$	261.00					\$	261.00
topan oracit in loader at	im oracica at right anni ora	oo mombor janotion	Ψ_	201.00					<u> </u>	201.00
*Weld bore if necessar	ry- done if bores cannot be	aligned during straightening.*	\$	1,566.00			\$	35.00	\$	1,601.00
									_	
nspection of machine to	ower bores and bucket lower	bores. Clean, measure.	\$	160.00					\$	160.00
Straighten hucket hores	and install new bearings.		\$	522.00	\$	186.36	\$	15.00	\$	723.36
oralginen buoket bores	and motali new bearings.		Ψ	022.00	Ψ	100.00	Ψ_	10.00	Ψ	720.00
Weld bore bucket			\$	913.50			\$	35.00	\$	948.50
Straighten links			\$	391.50					\$	391.50
Renlace quick coupler w	vith new, coupler cylinder, lo	cking pins, and lower pins	\$	476.75	\$	5,407.74			\$	5,884.49
topiaco quiot coupier w	mar now, coupler cymraci, ic	stang pino, and lower pine.	Ψ	170.70	Ψ	0, 107.7 1			Ψ_	0,001.10
Remove and install qty.2	2 lift cylinder for inspect, and	reseal. Reseal lines removed and	\$	783.00	\$	120.00			\$	903.00
replenish hydraulic oil.										
nspect and reseal qty.2	lift aulindors		\$	1,305.00	\$	350.00			\$	1,655.00
rispect and resear qty.2	iiit cylinders.		Ψ	1,303.00	Ψ	330.00			Ψ	1,033.00
nspect and reseal qty. 2	2 tilt cylinders.		\$	1,305.00	\$	370.00			\$	1,675.00
Travel To & From machi	ine.						\$	291.15	\$	291.15
nspection of damage to	machines lift arms						\$	317.25	•	317.25
inspection of damage to	maoriinos int arms.						Ψ	017.20	Ψ	017.20
Transport machine to Pa	atten Industries, and return t	o customer.					\$	600.00	\$	600.00
									_	
									-	

10/27/2011 1



## **Revised Quotation**

Co	omments				
Reference to work order TM22248. *Weld bore would be done only if necessary	/.*				
This quotation applies only to the specific items listed. No additional parts or servi	ces			Fet	imated Totals
will be performed unless authorized by the customer.			Standard Services:		149.50
		•	Labor:		
Proposed By: Wayne Miller 630-487-8308			Parts:		6,988.32
1 Toposcu by. Wayne Willion 600 407 6000			Misc.		1,293.40
Customer Signature:			Total:		21,101.47
oustomer dignature.			i otal.	Ψ	21,101.47
Estimate Date: 14-Oct-11					
		Customer	will be responsible t	or apr	olicable taxes.
PSSR Name: Kellen			,		
PSSR Email:					
PSSR Phone:					

\*Quotation Valid for 30 Days from Estimate Date\*

10/27/2011 2