

INDICATES PAVEMENT AREAS THAT SHOULD BE PATCHED (REMOVE & REPLACE BROKEN ASPHALT).

CANNOT FILL ANY HOLES HERE, AS PAVEMENT IS ALL CRUMBLING

PATCH PAVEMENT W/IN LIMITS OF PROPERTY

YES

INOPERABLE LIGHT POLE

ABOUT 11FT WIDTH OF ASPHALT TO BE REPLACED


YES

- NOTICED SEVERAL PARKING BLOCKS/WHEEL STOPS AROUND PARKING LOT. SINCE THE LOT IS CURBED, IT WOULD SEEM THESE BLOCKS SHOULD BE REMOVED.
- 3 SICK TREES @ SOUTH PROPERTY SHOULD BE REMOVED.
- REMOVE INOPERABLE LIGHT POLE & BASE FOUNDATION.

TYPICAL SIDEWALK

NOT TO SCALE

- NOTES
1. SURFACE TO BE A LIGHT BROOM FINISH AT RIGHT ANGLES TO THE EDGE OF THE SIDEWALK
 2. ASPHALTIC FELT EXPANSION JOINTS SHALL BE PROVIDED 30FT O.C WITH 1 2" DEEP CONTROL (FALSE) JOINTS 5FT O.C.
 3. SIDEWALK THROUGH ENTERENCE SHALL BE 6" THICK WITH 6x6xW1 4xW1 4 WWF



2 Site - Callout 1
1 1/2" = 1'-0"

Forma, Inc.

APEX design build

APEX DESIGN BUILD PRESENTS
OFFICE BUILDING RENOVATION
SHETH DERMATOLOGY
9131 W. 151ST-ORLAND PARK, 60462

15022
A1.0

KEVIN L 8-18-15