



Legislation Details (With Text)

File #: 2017-0270 **Version:** 1 **Name:** CPAC Tube Slide Vertical Turbine Repairs - Update
Type: MOTION **Status:** PASSED
File created: 4/7/2017 **In control:** Board of Trustees
On agenda: 5/1/2017 **Final action:** 5/1/2017
Title: CPAC Tube Slide Vertical Turbine Repairs - Update
Code sections:
Attachments: 1. Agenda Item 2017-0162, 2. Thomas Pump Quote

Date	Ver.	Action By	Action	Result
5/1/2017	1	Board of Trustees		
4/24/2017	1	Recreation and Parks Department	INTRODUCED TO BOARD	
4/17/2017	0	Parks and Recreation Committee		
4/7/2017	0	Recreation and Parks Department	INTRODUCED TO COMMITTEE	

Title
CPAC Tube Slide Vertical Turbine Repairs - Update

History

Update: This item (file number 2017-0162) was approved at the Board meeting on April 3, 2017. Upon further disassembly of the turbine, it has been determined that the impeller is beyond repair and the replacement and additional materials and labor will increase the cost from \$5,903.00 to \$7,987.00, an increase of \$2,084.00.

On April 17, 2017, this item was reviewed by the Parks & Recreation Committee, recommended for approval, and referred to the Village Board of Trustees for consideration.

Financial Impact

Funds for the additional repair costs are available in the 2017 Pool Budget account 283-4005-443200.

Recommended Action/Motion

I move to approve the additional parts and labor repair cost from Thomas Pump at a cost not to exceed \$2,084.00 for the additional repair work of the CPAC Tube Slide vertical turbine repair.

