

Robert H. **WARD & ASSOC., Inc.**

Concrete Repair

47<sup>th</sup> Year of Excellence

Shotcrete Specialists

November 6, 2008

Attn: Brian Madon  
Village of Orland Park  
Fax # 708-403-8798

Re: Curb Repair  
2009 Street Repair Program  
Orland Park, IL

We will provide, mobilization, labor, equipment, materials, and insurance to repair designated curb areas using our proprietary method of shotcrete repair for the following unit price:


Unit Price . . . . \$22.75/Lineal Foot

All repairs must be in neighborhoods where lane closures or traffic devices are not needed or required. We will provide barricades or markers for every location that we repair.

Measurement of the repairs for billing purposes, will be taken after the locations are prepared (chipped) to the extent necessary to remove all loose, cracked, defective, contaminated concrete to expose sound, clean surfaces. All repairs are measured by the length of the repair parallel to the face of the curb. **You will only be charged for actual repairs completed in place.**

The repair area, for measurement purposes, shall be defined as the outside limits of the concrete removal, after the preparation (chipping) is completed. The minimum measurement at any one repair location is One (1.0) Lineal Foot. If a repair location is longer than 1.0 Lineal Foot, then the measurement for that location will be taken in tenths of a foot - for example, 1.2 or 1.3 lineal feet. Over the years, the average measurement for each large crack has been 1.2 or 1.3 Lineal Feet. Broken edges of the flag (gutter) or rolled top area of the curb are usually longer. **Any areas that require complete removal and replacement are not covered by this proposal.**

Thank you for the opportunity to quote this work.

Sincerely  
  
Anthony P. Rago

PHONE 708-756-0767

3300 HOLLMAN AVE. SO. CHICAGO HEIGHTS, IL 60411

FAX 708-756-0940

[www.rhwardandassociates.com](http://www.rhwardandassociates.com)  
Equal Opportunity Employer