

SWC TECHNOLOGY PARTNERS**SWC Technology Partners**

1420 Kensington Rd.
Suite 110
Oak Brook, Illinois 60523
United States
<http://www.swc.com>
(P) 630-286-8121
(F) 630-572-0390

Quotation (Open)**Date**

Dec 27, 2016 01:11 PM
CST

Doc #

551556 - rev 1 of 1

Description

HPE Foundation Care Renewal, exp
3/21/17

SalesRep

Engers, Julie
(P) 630-371-9487
(F) 630-572-0390

Customer Contact

Johnson, Norm
(P) 708-403-6210
njohnson@orland-park.il.us

Customer

Village of Orland
Park (VO7443)
Johnson, Norm
14700 Ravinia Avenue
Orland Park, IL 60462
United States
(P) 708-403-6210

Bill To

Village of Orland Park
Johnson, Norm
14700 Ravinia Avenue
Orland Park, IL 60462
United States
(P) 708-403-6210

Ship To

Village of Orland Park
Johnson, Norm
14700 Ravinia Avenue
Orland Park, IL 60462
United States
(P) 708-403-6210

Customer PO:**Terms:**

Undefined

Ship Via:

FedEx Ground

Special Instructions:**Carrier Account #:**

Description	Qty	Unit Price	Total
1 HP Hardware Maintenance Onsite Support Hardware Problem Diagnosis; Onsite Support; Parts & Materials Provided; 24x7; Holidays covered; Travel Zone 1; Defective Media Retention	1	\$5,381.00	\$5,381.00
2 HP Software Technical Unlimited Support SW Technical Support; SW Electronic Support; 24x7; Holidays covered; Standard Response Time	1	\$1,776.00	\$1,776.00
3 HP Software Updates Service License to use & SW updates; HPE recommended SW upd method; HPE recommended doc upd method	1	\$924.00	\$924.00

Current Support Expires March 21, 2017

This covers the following:

HP 3PAR StoreServ, P/N QR489A, S/N MXN4110P89,
HP 3PAR 7000, P/N QR487A, S/N 2M241101YX,
HP 3PAR 7000, P/N QR487A, S/N 2M241101YT,
HP M6710, P/N QR492A, S/N 6C3404N1R1,
HP M6710, P/N QR492A, S/N 6C3404N1PP,
HP M6710, P/N QR492A, S/N 6C3404N1PZ,
HP M6710, P/N QR492A, S/N 6C3404N1LK,
HP M6710, P/N QR492A, S/N 6C3404N1LL,
HP M6710, P/N QR492A, S/N 6C3404N1LJ,
HP M6710, P/N QR492A, S/N 6C3404N1R5,
HP M6710, P/N QR492A, S/N 6C3404N1SU,
HP M6710, P/N QR492A, S/N 6C3404N1SR,
HP M6710, P/N QR492A, S/N 6C3404N1SN,
HP M6710, P/N QR492A, S/N 6C3404N1MK,
HP M6710, P/N QR492A, S/N 6C3404N1MB,
HP M6710, P/N QR492A, S/N 6C3404N1MG,
HP M6710, P/N QR492A, S/N 6C3404N1MC,
HP M6710, P/N QR492A, S/N 6C3404N1ML,
HP M6710, P/N QR492A, S/N 6C3404N1ME,
HP M6710, P/N QR492A, S/N 6C3404N1PU,
HP M6710, P/N QR492A, S/N 2M24080100,
HP M6710, P/N QR492A, S/N 6C3404N1MA,

Subtotal: \$8,081.00
Tax (0.000%): \$0.00
Shipping: \$0.00
Total: \$8,081.00

HP M6710, P/N QR492A, S/N 6C3404N1MD,
HP M6710, P/N QR492A, S/N 6C3404N1MH,
HP M6710, P/N QR492A, S/N 6C3404N1MJ,
HP M6710, P/N QR492A, S/N 6C3404N1SP,
HP M6710, P/N QR492A, S/N 6C3404N1SS,
HP M6710, P/N QR492A, S/N 6C3404N1ST,
HP M6710, P/N QR492A, S/N 6C3404N1SV,
HP M6710, P/N QR492A, S/N 6C3404N1SB,
HP M6710, P/N QR492A, S/N 6C3404N1SC,
HP M6710, P/N QR492A, S/N 6C3404N1S9,
HP M6710, P/N QR492A, S/N 6C3404N1S1,
HP M6710, P/N QR492A, S/N 6C3404N1RT,
HP M6710, P/N QR492A, S/N 6C3404N1R6,
HP M6710, P/N QR492A, S/N 6C3404N1PY,
HP M6710, P/N QR492A, S/N 6C3404N1PN,
HP M6710, P/N QR492A, S/N 6C3404N1PS,
HP M6710, P/N QR492A, S/N 6C3404N1N6.

All prices are subject to change without notice. Supply subject to availability.
Shipping costs are estimates and could vary.