

Village of Orland Park Bid Responsiveness Check

Bid #: 19-014

Project Title: Salt Storage Building Glass Block Replacement

Bid Requirement	3F Corporation	Krull Window Company Inc.	Replacement Window Systems Inc.		
Submitted three (3) sealed hardcopies of the bid	√	√	√		
Submitted a completed Bidder Summary Sheet	√	√	√		
Submitted a completed Certificate of Compliance	√	√	√		
Submitted three (3) references	√	√	√		
Submitted signed Insurance Requirements form	√	√	√		
Bid Amount	\$77,800.00	\$67,211.00	\$83,675.00		

*A check mark in the box indicates inclusion of the required form with the proposal package. A "V#" indicates a variance that will be explained below.

Prepared by: Denise Domalewski, Purchasing Administrator - Village of Orland Park