

ROCK OUTCROPPING



GRANITE BOULDERS



WEATHERED ROCK OUTCROPPING





Notes:

*Water Quality Improvement

*Soil Erosion Protection through Native Vegetation *\$300,000 Total Cost *Sight Line to Water and Hardscape Features

*Improved Fish Habitat

*6-8 Foot water depth at center

06-20-2018 TAF