



2033 WEST WALNUT STREET CHICAGO, IL 60612
312/829-1919 FAX 312/829-6142

INTERNET: <http://www.standardequipment.com>
E-MAIL: sales@standardequipment.com

A34269

70306

7/31/12 8:03 2

VILLAGE OF ORLAND PARK
14700 S. RAVINIA AVE
ATTN: ACCOUNTS PAYABLE
ORLAND PARK IL 60462

VILLAGE OF ORLAND PARK
15655 S RAVINIA AVE
ORLAND PARK IL 60462

708/403-6350

001	VT 2110-J4	01-10V-7919	800 004 PO#	7/16/12
1	1	NS 2002	FAST, NUT *	96 96
1	1	NS 2009	COTTER/HAIR PIN *	40 40
1	1	NS 5000	MISC, CLAMP *	211 211
5	5	NS 5002	MISC, TIE STRAP *	123 615
1	1	NS 6000	O-RING, RUBBER *	145 145
4	4	VA 29323	TRUSS ROD, THREADED C323 *	18340 73360
2	2	VA 29384D	CHECK VALVE 3 A4501 *	47738 95476
2	2	VA 29385	CHECK VALVE - 2 A4505 *	34048 68096
8	8	VA 29644	NUT HEX 1 1/2" -12A4404 *	764 6112
3	3	VA 29662	SEAL, SENSING ROD A4513 *	517 1551
1	1	VA 29678	YOKE, SENSING ROD, SA4509 *	5524 5524
2	2	VA 37495A	SEAL KIT WATER / OA4209 *	16113 32226
2	2	VA 40314	LOCKWASHER - HI-COA4308 *	17 34
1	1	VA 41717	CYLINDER BARREL, WAC424 *	2,51200 2,51200
1	1	VA 45727	BAND CLAMP T/BOLT A4605 *	620 620
10	10	VA 45824	HOSE, WATER, 3XBULK C541 *	1801 18010
1	1	VA 45834	SENSOR - PROXIMITY A4810 *	22130 22130
1	1	VA 55787	PISTON ASSEMBLY *	2870 2870
1	1	VA 55790	SEAL RETAINER /SIM *	1782 1782
1	1	VA 62112	CENTER BLOCK C531 *	1,87765 1,87765
		TOTAL PARTS		8,04421
24		FIRM PRICE LABOR		11200 2,68800
		SUPPLY/TOOL/EPA CHARGE		1500
		NON-TAXABLE MUNICIPAL		N/C
		E9998-1807-04		

Signature

Date

10,74721



2033 WEST WALNUT STREET CHICAGO, IL 60612
312/829-1919 FAX 312/829-6142

INTERNET: <http://www.standardequipment.com>
E-MAIL: sales@standardequipment.com

A34269

70306

7/31/12 8:03 1

VILLAGE OF ORLAND PARK
14700 S. RAVINIA AVE
ATTN: ACCOUNTS PAYABLE
ORLAND PARK IL 60462

VILLAGE OF ORLAND PARK
15655 S RAVINIA AVE
ORLAND PARK IL 60462

708/403-6350

001 VT 2110-J4 01-10V-7919

800 004 PO#

7/16/12

Telephone 708/403-6350

PER YOUR REQUEST WE WILL PER FORM THE FOLLOWING:

ATTN: TOM MORGAN CELL 708-362-2370 W 708-403-6350

CHECK RODDER PUMP HAMMERS, CHECK RELIEF VALVE - PSI DROPS ON ONE SIDE. CHECK HAND GUN PRESSURE.

CORRECTION: VARIFIED CUSTOMERS CONCERN, FOUND THAT THE RODDER PUMP NEEDS TO BE REBUILT. UPON TEAR DOWN THE TECH FOUND THAT THE CENTER BLOCK SEAL FAILED AND FOUND PITTING IN THE CENTER BARREL. REINSTALLED RODDER PUMP AFTER COMPLETING THE REBUILD, FLUSHED THE SYSTEM OUT AND SET TO SPECS PERFORMS NORMAL NOW.

WATER DRIPS FROM WEEPHOLES

CORRECTION: SEE ABOVE REPAIR

1	1	IS 2499A34	4" CUTOFF WHEEL	A6606 *	701	701
1	1	IS 82507	DRILL BIT 7/64	A6106 *	454	454
1	1	IS 82508	DRILL BIT 1/8	A6106 *	468	468
1	1	IS 87AT	BRAKE PARTS CLEANECHEM C*		395	395
15	15	IS 9005	FLU,AW46 HYD OIL	SHOP *	1095	16425
15	15	IS 9005	FLU,AW46 HYD OIL	SHOP *	1095	16425
1	1	IS AB600	SPRAY BLACK GLOSS	A6906 *	539	539
1	1	IS AB699	SPRAY PRIMER GRAY	A6614 *	539	539
3	3	NS 2001	BOLT/SCREW	*	153	459
1	1	NS 2001	BOLT/SCREW	*	153	153

CONTINUED