





Existing Tree Inventory:

TAG #	BOTANICAL NAME	COMMON NAME	TREE SIZE	CONDITION	COMMENTS	Replacement Trees
291	Ulmus pumila	Siberian Elm	14" Cal.	Poor		0
292	Acer saccharinum	Silver Maple	36" Cal.	Poor	Trunk Decay	0
293	Acer saccharinum	Silver Maple	24" x 24"	Poor	Trunk Decay	0
294	Prunus virginiana	Chokecherry	10" Cal.	Poor		0
295	Prunus virginiana	Chokecherry	8" Cal.	Poor		0
296	Acer saccharinum	Silver Maple	6" - 10"	Poor	Multi Stem (5)	0
297	Malus spp.	Apple	14" Cal.	Poor	Trunk Decay	0
298	Betula nigra	River Birch	4" Cal.	Good	Multi Stem (4) 4" Cal. Stems	1 @ 4" Caliper
299	Betula nigra	River Birch	4" Cal.	Good	Multi Stem (4) 4" Cal. Stems	1 @ 4" Caliper
300	Betula nigra	River Birch	4" Cal.	Good	Multi Stem (4) 4" Cal. Stems	1 @ 4" Caliper
301	Betula nigra	River Birch	4" Cal.	Good	Multi Stem (4) 4" Cal. Stems	1 @ 4" Caliper
302	Acer platanoides	Norway Maple	6" Cal.	Good		0
303	Gleditsia triacanthos inermis	Thornless Honeylocust	6" Cal.	Good		0
304	Acer platanoides	Norway Maple	6" Cal.	Good		0
305	Pyrus calleryana	Callery Pear	8" Cal.	Good		1 @ 4" Caliper
Total Replacement Trees 5						



Shaded tree symbols indicate existing trees to be removed.

Tree symbols that are not shaded indicate existing trees to remain.

